# YU5010A Flashing Procedure

If you want to flash CM software to Android version, you should install USB and drivers you also need to install flash tool in your PC

Follow the below steps

1. Install USB driver

2. Install adb driver

3. Install tool

4. How to flash

1. Install USB driver

Install USB driver very simply, Open usb driver file and setup, then you only need to choice next.

YU5010A Flashing Procedure

YU5010A Flashing Procedure

YU5010A Flashing Procedure

2. Install adb driver

1. Copy this adb files to your PC the route is C:\Windows\System32.
2. Connected phone with PC USB and open PC devices manage

YU5010A Flashing Procedure

Open devices manage Now you see adb driver install successful

3. Install flash tool (QPST)

1. Install QPST tool very simply, Open QPST file and setup, then you only need to choice next step the same with USB driver

YU5010A Flashing Procedure

YU5010A Flashing Procedure

4. How to flash

1. Frist press volume up key then press power key in power off mode to enter fast boot mode.

2. Then run unlock.bat

|			
adb.exe	5,414 KB	2015/4/24 16:10	应用程序
AdbWinApi.dll	94 KB	2015/4/24 16:10	应用程序扩展
AdbWinUsbApi.dll	60 KB	2015/4/24 16:10	应用程序扩展
cmd.exe	296 KB	2010/11/21 5:29	应用程序
debuggable.img	18,460 KB	2015/5/13 12:06	光盘映像文件
EnableEDL.bat	1 KB	2015/5/15 21:04	Windows 批处理...
erase config.bat	1 KB	2015/11/6 16:58	Windows 批处理...
erase config.rar	2,094 KB	2015/11/6 16:59	WinRAR 压缩文件
fastboot.exe	851 KB	2015/4/24 16:15	应用程序
step.txt	1 KB	2015/9/26 13:23	文本文档
unlock.bat	1 KB	2015/11/24 15:00	Windows 批处理...
新建文本文档.txt	0 KB	2015/11/6 16:58	文本文档

Fastboot Mode   Run unlock.bat

2.Open QFIL then import software.

To check QPST tool>> Go to>>C drive>>Program File (X86)>>Qualcomm>>QPST>>bin>>qfil

YU5010A Flashing Procedure

# YU5010A Flashing Procedure

Clicked this item 2 times

3. After finishing download reboot devices