Guide for SW Upgrading

Contents

- 1. Equipment required
- 2. Notice
- 3. Installation
- 4. Upgrade SW

1.Equipment required

item	Description
①Computer	To install driver/ upgrade SW
②Update tool	OEM_Download Factory(1.0.0.6)_Setup.exe
③Data cable	5pin Micro USB cable
4OS supported	Windows 2000/XP/Vista/ Seven
⑤ Driver	QSC1105_USB_Driver

2.Notice

- Do not disconnect USB cable when updating the SW
- If you change to use other USB port or another PC, please check the COM port No. first before updating.
- If the handset dead when updating SW, please using Emergency download to rescue it

3.Installation

- Install QSC1105 driver (the folder "QSC1100_USB_Driver") first when you first time connect the phone with PC
 - 1. ---Device Manager---find "other devices" or yellow mark





2. Install the driver as these step:







Remember the COM No. in Device manager Secondly, install the Download tool which named "OEM_Download Factory(1.0.0.6)_Setup" following the steps as below:



4.Upgrade SW

Double click the Icon in the desktop





If need to use Upgrade Mode, please locate the correct BIN/SCR /DLL files

		(COM Port Sel	ect			
-Auto-Select Manual-	Select	at set	1.51E	1.546	1.114	- 1944	Market .
	1 🗌 СОМ2	🗆 сомз	🗆 сома	🗆 сом5	🗆 сомб	🗆 сом7	🗆 сомв
1~8	9 🗆 сом10	□ сом11	□ сом12	□ сом13	□ сом14	Сом15	□ сом16
9 [~] 16 □ COM	17	□ сом19	□ сом20	□ сом21	□ COM22	Сом23	□ COM24
□ 17 ⁻ 24 □ 25 ⁻ 32 □ СОМ	25 🗆 сом26	□ сом27	□ сом28	🗆 сом29	□ сомзо	🗆 сомзі	Г сомз2
ConfigDo □ CalCheck □ Cal BackupDo	nlow Setting voioad Mode Upgrade C Bl	N Download	C SCR Dow	nload C PR	L Download (C Emergency	C Info Checl
Brew Write	Bin Select	If Moo	need t de , ne	co use deed to	Upgrade locate		
Brew Write Erase All Develop Config	Bin Select	If Moo BIN	need t de , ne N/SCR/D	co use ed to DLL fil	Upgrade locate es		
□ Brew Write □ Erase All Develop Config □ Make Binary	Bin Select		need t de , ne N/SCR/D	co use ed to OLL fil	Upgrade locate es		





The handset will reboot automatically in the procedure, **Do not disconnect** the Handset from PC , until it show **Success download.** It will take about 6 to 10 minutes



This tool support multiple download, it can be upgraded SW for 2 or more Handsets in the same time. It need to choose the correct COM port No. as like that:

Auto-Selec	_ ⊢ Manual-Sele	ect		OM FUIL SEI	CL1			
E All	🗆 сом1	Г сом2	🔽 сомз	🖾 сома	🔽 сом5	🗆 сомб	🗆 сом7	🗆 сомя
□ 1 [~] 8	🗆 сомя	Г сом10	. сом11	Г сом12	🔽 сом13	🗆 сом14	🗆 сом15	🗆 сом16
□ 976 □ 17°24	🗆 СОМ17	Сом18	□ сом19	🗆 сом20	□ сом21	🗆 сом22	🗆 сом23	🗆 сом24
□ 17 24 □ 25~32	🗆 СОМ25	СОМ26	Г СОМ27	🗆 сом28	🗆 СОМ29	🗆 сомзо	🗆 сомзі	🗆 сомза

Emergency download

If the handset dead when updating SW, it need to use Emergency Download to fix it

Setting for Emergency mode

up							
			OM Port Sel	ect			
-Auto-Select M	anual-Select						
	СОМ1 🗆 СОМ2	🗆 сомз	🗆 сома	🗆 сом5	🗆 сомб	🗆 сом7	🗆 сомв
🗌 1~8 🛛 🔽	сомя 🗆 сом10	□ сом11	□ COM12	□ COM13	□ COM14	Г сом15	Сом16
	СОМ17 🗆 СОМ18	□ сом19	Г сом20	□ COM21	□ COM22	Г сом23	COM24
□ 17 24 □ 25 ^{°°} 32	СОМ25 🗆 СОМ26	С СОМ27	С СОМ28	С СОМ29	□ сомзо	□ сомз1	🗆 сомз2
Config	– Download Setting –						
	-Download Mode						
Calcheck	○ Upgrade ○ BI	N Download	C SCR Dow	nload C PR	L Download	Emergency	Info Check
🔽 Cal Backun					L		
	Download Items						1
Brew Write	Bin Select	\Infinitvinfo\[008\友慣炊件	SUBH\D081	SD00 OPERT	EST 2013041	6\130416PMDI
🗖 Erase All							
Develop Config							
Make Binary							
OEM Internal	DII Select D:	\Infinityinfo\[208\友恺软件	SUBH\D081	SD00_OPERT	EST_2013041	6\CG105L_No_
Download Tools							
		ок			Са	ncel	
	1						

- 1. Disconnect USB cable first , and pull out the battery.
- 2. Press the key of "1" and holding it until step 4
- 3. Connect handset to PC using USB cable
- 4. Find the COM port No. in Device Manager, then unhold the key "1"
- 5. Set the configuration as the picture above, using the same BIN/DLL file
- 6. Press start button to begin

After finish Emergency download, disconnect the handset, and plug into PC again Using SRC mode to upgrade SRC file.

CalCheck	Download Mode
🔽 Cal Backup	Download Items
E Brew Write	
🗆 Erase All	SCR Select
Develop Config	PRL Select NULL
🗆 Make Binary	
OEM Internal Download Tools	DII Select D:\Infinityinfo\D08\友恺软件\SUBH\D081SD00_OPERTEST_20130416\CG105L_No_

Then it is the completed procedure for Emergency rescue